

Number: GZHT02326037

| Report Ref: | GZHT02326037 | | |
|----------------|--------------|--------------|--------------|
| Date Received: | Aug 12, 2020 | Date Issued: | Aug 18, 2020 |

Company Name: MKTO CATAL IMPORTACIONES S.L.

Address: CTRA.HUERCAL-OVERA

S/N ES-04640 PULPI ALMERIA

SPAIN

Contact Name: CELINA

| The Following Sample Was Subm | itted And Identified By/On Behalf Of The Applicant As: | | |
|-------------------------------|--|--|--|
| End Uses : | Non-Sterile Medical Face Mask | | |
| Ratings : | : Type IIR | | |
| Sample Name : | Disposable Mask | | |
| No. Of Sample : | One(15 pieces) | | |
| Size : | - | | |
| Colour : | Black | | |
| Standard : | EN 14683:2019+AC:2019 | | |
| Buyer : | MKTO CATAL IMPORTACIONES S.L. | | |
| Date received/ Test Started : | Aug 12, 2020 | | |
| Ref : | Lot No.: Item 6634 | | |

Test was conducted on specific items, at our client's request.

Prepared And Checked By:

For Intertek Testing Services Shenzhen Ltd. Guangzhou Branch

Lin Lin

General Manager

AL / pennytao



Page 1 Of 5

Intertek Testing Services Shenzhen Ltd. Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司

Room 02, 1-8/F & Room 01, E101/E201/E301/E401/E501/E601/E601/F30/E601/R001, No.7-2, Caipin Road, Guangzhou Science City, GETDD, Guangzhou China 中国广州经济技术开发区科学城彩频路 7 号之二第 1—8 层 02 房

E201、E301、E401、E501、E601、E701、E801


Tel: +86 20 8213 9001 Fax: +86 20 8208 9909 Postcode: 510663

Hengyun Building, 235 Kaifa Ave., Guangzhou comic & Technological Development District, Guangzhou, China 中国广州经济技开发区开发大道 235 号恒运大厦 3 楼

: +86 20 8396 6868 Fax: +86 20 8222 8169 Postcode: 510730



Number: GZHT02326037



Prepared And Checked By: For Intertek Testing Services Shenzhen Ltd. Guangzhou Branch

Lin Lin General Manager

AL / pennytao

Page 2 Of 5

Intertek Testing Services Stienzhen Ltd. Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司

Room 02, 1-8/F & Room 01, E101/E201/E301/E401/E501/E601/F79/16801, No.7-2, Caipin Road, Guangzhou Science City, GETDD, Guangzhou Shina 中国广州经济技术开发区科学城彩频路 7 号之二第 1—8 层 02 房 91 房 101.

E201、E301、E401、E501、E601、E701、E801

Tel: +86 20 8213 9001 Fax: +86 20 8208 9909 Postcode: 510663

Hengyun Building, 235 Kaifa Ave., Guangzhou comic & Technological Development District, Guangzhou, China 中国广州经济技开发区开发大道 235 号恒运大厦 3 楼

: +86 20 8396 6868 Fax: +86 20 8222 8169 Postcode: 510730



Number: GZHT02326037

Summary of testing:

With reference to following standard:

EN 14683:2019+AC:2019 Medical face masks – Requirements and test methods Type IIR

Materials Used in The Submitted Sample Were Found To Comply With The Type IIR Requirements of EN 14683:2019+AC:2019 with respect to Bacterial Filtration Efficiency and Differential Pressure test.

Prepared And Checked By:

For Intertek Testing Services Shenzhen Ltd. Guangzhou Branch

Lin Lin

General Manager

AL / pennytao



Page 3 Of 5

Intertek Testing Services Shenzhen Ltd. Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司

Room 02, 1-8/F & Room 01, E101/E201/E301/E401/E501/E601/F791/E601, No.7-2, Caipin Road, Guangzhou Science City, GETDD, Guangzhou 中国广州经济技术开发区科学城彩频路7号之二第1-8层02房、 的憲

東国广州经济技开发区开发大道 235 号恒运大厦 3 楼

Hengyun Building, 235 Kaifa Ave., Guangzhou

e: +86 20 8396 6868 Fax: +86 20 8222 8169 Postcode: 510730

conomic & Technological Development District, Guangzhou, China

E201、E301、E401、E501、E601、E701、E801

Tel: +86 20 8213 9001 Fax: +86 20 8208 9909 Postcode: 510663



Tests Conducted (As Requested By The Applicant)

Number: GZHT02326037

Differential Pressure (EN 14683:2019+AC:2019 Annex C): Air flow: 8L/min, Test area diameter 25 mm, Test area: 4.9 cm².

| <u>Tested</u> <u>Sample</u> | Result (Pa/cm²)* | | | | <u>Performance</u> <u>Requirement for Medical</u> Face Mask (Pa/cm ²) | |
|--|------------------|------------|------------|------------|---|----------------|
| | Specimen 1 | Specimen 2 | Specimen 3 | Specimen 4 | Specimen 5 | |
| Location 1 | 43.0 | 45.0 | 38.8 | 41.9 | 40.8 | |
| Location 2 | 40.3 | 42.1 | 39.6 | 39.7 | 40.5 | |
| Location 3 | 41.8 | 43.4 | 42.8 | 46.3 | 43.4 | Type IIR: < 60 |
| Location 4 | 41.2 | 42.9 | 38.8 | 42.2 | 45.7 | |
| Location 5 | 39.1 | 38.5 | 46.0 | 37.6 | 41.7 | |
| Average | 41.1 | 42.4 | 41.2 | 41.5 | 42.4 | |
| * = All the locations were evenly taken from the main mask body. | | | | | | |

AL / pennytao

Page 4 Of 5

Intertek Testing Services Stienzhen Ltd. Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司

Room 02, 1-8/F & Room 01, E101/E201/E301/E401/E501/E601/F20 / E301, No.7-2, Caipin Road, Guangzhou Science City, GETDD, Guangzhou, Brina中国广州经济技术开发区科学城彩频路 7 号之二第 1—8 层 02 房 101、

E201、E301、E401、E501、E601、E701、E801

Tel: +86 20 8213 9001 Fax: +86 20 8208 9909 Postcode: 510663

Hengyun Building, 235 Kaifa Ave., Guangzhou promic & Technological Development District, Guangzhou, China 中国广州经济技开发区开发大道 235 号恒运大厦 3 楼

: +86 20 8396 6868 Fax: +86 20 8222 8169 Postcode: 510730



Tests Conducted (As Requested By The Applicant)

Number: GZHT02326037

2 Bacterial Filtration Efficiency (BFE)

As Per EN 14683:2019+AC:2019 Medical face masks – Requirements And Test Methods Annex B.

| | | <u>Performance</u> | | | | |
|------------|--------------|--------------------|--------------|-----------------|-----------------|---------------------|
| Tost Itom | | Requirement for | | | | |
| Test Item | Specimen (1) | Specimen (2) | Specimen (3) | Specimen (4) | Specimen (5) | <u>Medical Face</u> |
| | | | | | | <u> Mask (%)</u> |
| Bacterial | | | | | | |
| Filtration | >99.9 | >99.9 | >99.9 | >99.9 | 99.9 | Type IIR: ≥98 |
| Efficiency | | | | | | ,. |
| (BFE) | | | | | | |

Remarks:

- 1. Biological Aerosol: *Staphylococcus aureus* (ATCC 6538).
- 2. Testing side: Inside of the test specimen was facing towards the challenge aerosol.
- 3. Test area: 78 cm² 4. Flow rate: 28.3 L/min
- 5. The average plate count results of the positive controls: 2.0×10^3 CFU
- 6. The average plate count results of the negative controls: < 1 CFU
- 7. CFU = Colony Forming Unit

Remark: This test item was conducted in Caipin Road, Guangzhou Science City, GETDD, Guangzhou, Guangdong.

End of Report

This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or wilful misconduct. No copy of the test report(except for full text copy) shall be made without the written approval by Intertek.

AL / pennytao

Page 5 Of 5

Intertek Testing Services Strenzhen Ltd. Guangzhou Branch

3#E

深圳天祥质量技术服务有限公司广州分公司

Room 02, 1-8/F & Room 01, E101/E201/E301/E401/E501/E601/F701/E801, No.7-2, Caipin Road, Guangzhou Science City, GETDD, Guangzhou, China 中国广州经济技术开发区科学城彩频路7号之二第1-8层02房、 9月房 101、

E201、E301、E401、E501、E601、E701、E801

Tel: +86 20 8213 9001 Fax: +86 20 8208 9909 Postcode: 510663

: +86 20 8396 6868 Fax: +86 20 8222 8169 Postcode: 510730

conomic & Technological Development District, Guangzhou, China

Hengyun Building, 235 Kaifa Ave., Guangzhou

中国广州经济技开发区开发大道 235 号恒运大厦 3 楼